



SmallFit® : 14mm PAL

75/80 SmallFit



L

R

Fig. A. Fitting heights positioned too low can result in loss of useable reading area—one of the most common causes of nonadapts. To ensure proper positioning, place fitting cross marks over the midpupil. Check to be sure that the vertical fitting height is a minimum of 14mm

Minimum suggested fitting height is 14mm.